

Installation procedure:

- 1. Connect the HDMI and USB ports of the receiver of the wireless transmitter to the display device such as the TV or projector.
- 2. Connect the HDMI and USB ports of the transmitter of the wireless transmitter to the display device such as laptops. desktops, set-top box cameras, and camcorders.
- 3. After the connection is complete, the blue light of the transmitter will blinks first, and becomes steady. When the connection is successful, the screen will show the video.

- 1. Equipment operating temperature: About 50 degrees ,but it is normal t emperature which does not affect the use.
- 2. The device has been paired before leaving the factory, and the user does not need to re-pair.
- 3. The RX light at the receiving end will not flash and only serves as a power indicator light

FH-WD9906

Wireless Transmitter Pairing Method

Pairing Steps

1 Receiver side

- (1) Connect the receiver USB port to the USB power supply or device with USB port
- (2) Connect the receiver HDMI port to the display device
- (3) use a paperclip to press the reset button on HDMI side of the receiver for about 2 seconds (not so long), wait for the screen to display "Release the button to pair with Mate" then immediately release the button



2 Transmitter side

(1)Connect the transmitter USB port to a USB-powered device, and wait for the screen to display "Ready to pair".

(2) Use a paperclip to insert the pairing/reset hole at the HDMI end and press the pairing button for 5 seconds, wait until the signal light goes off and release the button.

(3) Then wait for the screen to show "J" to indicate successful pairing.




Attention:

The reset hole on the receiver side of the wireless transmission has two setting modes depending on the pressing time.

- (1) Press and hold for 2 seconds: open the pairing mode of the receiver for pairing with the transmitter, so the pairing pairing can not be pressed for too long
- (2) long press 10 seconds: the receiver back to the original factory settings.





安装 步骤:

- 1.将无线传输器接收端HDMI和USB端口连接至电视机或者投影仪 等显示设备
- 2.将发射端HDMI和USB端口接上笔记本电脑、台式机、机顶盒、 相机、摄像机等信号源
- 3. 接好后发射端蓝灯先闪烁, 连接成功后变常亮, 屏 墓出现图像

注意事项:

- 1. 设备工作温度: 50 度左右, 属于正常温度不影响 使用
- 2. 设备出厂前已配对好, 在不能使用的情况下, 再重 新配对
- 3. 接收端灯不会闪烁,仅作电源指示灯

FH-WD9906

无线传输器配对方法

配对步骤

1 接收端

- (1) 将无线传输器的接收端的USB端连接至USB供电或设备USB接口。
- (2) 将无线传输器的接收端HDMI接上显示设备
- (3) 使用回形针长按接收器HDMI端的重置孔配对按键2秒左右(不能按时间太
- 长) . 等待屏墓显示Release the button to pair with Mate时马上放开按钮



2 发射端

将发射器USB□接上USB供电设备, 等在屏幕上显示 "Ready to pair" 时, 使用回形针插入位于HDMI端的配对/重置孔配对按键长按5秒、待信号灯熄灭松 开按键,等待屏幕出现打"√"表示设备配对成功。



注意:

无线传输接收端上的重置引,根据按压时间不同,有两种设定模式。

- (1) 长按2秒: 开启接收器的配对模式, 供与发射器进行配对, 所以配 对不能按时间太长
- (2) 长按10秒: 将接收器回复原厂设定。